

2018 KIA RIO

Vehicle Feature Tips

Many of the Tips presented below are covered in greater detail in the Owner's Manual, Multimedia System Manuals, Features and Functions Guide and Quick Start Guide hang-tag supplied with your new vehicle.





2018 Rio 5DR SX shown

Voice Recognition and Bluetooth®1

Using Voice Recognition on UVO eServices System*

Improve Bluetooth®1 Voice Recognition (VR) performance by making a few simple changes to your phone contacts:

- Use full names (first and last names) vs. short or single syllable names ("John Smith" vs. "Dad", "Smith Residence" vs. "Home").
- Avoid using special characters, emojis, and hyphenated names (@, &, #, /, -, *, +, etc.).
- Avoid using acronyms ("Emergency" vs. "ICE" or "In Case of Emergency") or words with all capital letters.
- Spell words completely; system will not recognize abbreviations ("Doctor Smith" vs. "Dr. Smith").
- Always wait for the beep before speaking any commands.
- When using VR to place a call, speak in a natural, moderate tone, with clear pronunciation. The system may have trouble recognizing commands if you speak too soft or too loud.
- Ask about this changing to sunroof also per other book markups.
- Your VR system may have difficulty understanding some accents or uncommon names.
- Press the talk button and say "Help" to get a list of available commands.

Pairing or Connecting Your Phone with Bluetooth*

- Press the Phone hard key (if equipped) or "Call" button on the steering wheel to begin the pairing process if no phone has previously been paired.
- To pair a second phone or subsequent phones, reference the manuals and guides supplied with your Rio as steps vary by radio.

- During the pairing process, please make sure you accept all requests for phonebook download and future autoconnection on your phone.
- If you experience any issues with auto-connection, try the following:
 - Reboot your phone (turn the phone off and then on).
 - Update the phone operating system to the most recently released version.
 - Delete the phone from the radio and the radio from the phone, and re-pair.
 - Ensure the phone has the Bluetooth®1 feature activated.
- If some contacts are not downloading to the radio, check to confirm that the contact has been entered correctly and that it has been stored under the categories (HOME, MOBILE, WORK, iPhone^{®2}) that are supported by the radio. Some contact categories (MAIN, PAGER, OTHER) may not be supported. If the number of contacts exceeds the maximum number allowed on the radio, contacts will be partially downloaded. Ensure that only the "phone contact list" is selected for contact download on your phone (not social media or email contact lists as these contacts may not download to the radio).
- Phone operating systems change frequently and some phones may have varying compatibility levels with the Bluetooth® system. For any questions regarding the features of your vehicle, please contact your preferred Kia dealer or contact Kia Consumer Assistance at 1-800-333-4542.

Other Bluetooth®1 Tips

- Bluetooth® reception is affected by carrier coverage and is dependent on the phone.
- If streaming audio through Bluetooth $^{\rm @1}$ from a device, ensure the listening volume on the device is turned up.

QR Code

To view a video on your mobile device, snap this QR Code or visit the listed website. https://www.youtube.com/KiaFeatureVideos



Connecting to Apple CarPlay[™] and Android Auto^{™2*} on UVO eServices System



Apple CarPlay™

Your vehicle offers you effortless command of your compatible iPhone® when you connect through Apple CarPlay™ on your UVO display. This will enable you to make calls, send hands–free texts, access your favorite music and apps, and get navigation help with Siri® voice control.

To connect Apple CarPlay, visit https://youtu.be/N1FQ1VqDt4A.



Android Auto™

Your vehicle allows you to connect to your compatible AndroidTM phone via Android AutoTM on your UVO display. Through this feature, you can access music, your phone's dialer, navigation help and more with an intuitive interface and voice commands. You can even access your phone through your steering wheel controls. To connect Android Auto, visit https://youtu.be/QPV7y06-RJ4.


Satellite Radio Reception



Satellite radio reception requires direct line of sight with the satellite transmitting the radio signal. Tunnels, bridges, covered parking, mountainous terrain, tall buildings, heavy foliage, and other obstacles may momentarily interrupt the signal. This is normal operation, and reception will be restored within a few seconds in an open, unobstructed area.


The signal can become weak in some areas that are not covered by the satellite repeater network.

Trunk/Tailgate Operation



The trunk/tailgate is locked or unlocked when all doors are locked or unlocked with the key fob or central door lock switch. If unlocked, the trunk/tailgate can be opened by pressing the handle and pulling it up. When all doors are locked, if the trunk/tailgate unlock button on the key fob is pressed momentarily, the trunk/tailgate will unlock; if pressed for more than 1 second, the tailgate automatically opens.

Tilt/Telescoping Steering Wheel*



To adjust the Steering Wheel:


- Push down on the Lock-Release Lever (A).
- Adjust the Steering Wheel to the desired angle (B).
- Adjust the Steering Wheel distance (C).
- Pull up the Lock-Release Lever (A) to lock the Steering Wheel in place.

It may be helpful to lift the Steering Wheel up while moving it toward/away from you to adjust to the desired distance.

Wind Buffeting

In many vehicles, when a rear window is lowered and the front window(s) are in the closed position, air flowing past the open window(s) induces pressure oscillations, or pulsations, which may be uncomfortable. When opening the rear window(s), always remember to also open the front window(s), slightly, to relieve the pressure oscillations inside the vehicle.


Lighting Stalk Operation



(A) OFF position

- (B) Auto light position
- (C) Parking light position
- (D) Headlight position

The light switch has a Headlight, Auto light and a Parking light position. To operate the lights, turn the knob at the end of the control lever to one of the above positions.




When the light switch is in the parking light position (C), the tail, license and instrument panel lights will turn ON.

Fog Lights*: Fog lights are designed to help improve visibility when visibility is poor due to fog, rain or snow, etc. The fog lights will turn on when the fog light switch (E) is turned to the on position after the headlights are turned on.

To turn off the fog lights, turn the switch (E) to the off position. When in operation, the fog lights consume large amounts of the vehicle's electrical power. Only use the fog lights when visibility is poor.

Front and Rear Windshield Wiper/Washer Controls



MIST: Single wipe


OFF: Wiper off

INT: Intermittent wipe

LO: Slow wipe

HI: Fast wipe

PULL: Spray and wipe



HI: Fast wipe

LO: Slow wipe

OFF: Wiper off

PUSH: Spray and wipe

Check Engine Light from Fuel Cap




Tighten the cap until it clicks one time; otherwise, the Check Engine Light (may illuminate.

The Fuel Filler Door Release lever is located on the lower part of the driver's door sill.




Headrest Adjustments



- · To raise headrest: Pull headrest up.
- To lower headrest: Press lock, then press the headrest down.

Windshield Defogging




Windshield fogging is caused by moisture in the air condensing on the cold glass. To help reduce window fogging:

- Keeping the inside of the glass as clean as possible.
- Utilizing the Defrost Mode activates the A/C and opens Fresh Air Vent (A).
- Adjusting the Temperature Control to the desired temperature (B).

Condensation Inside Exterior Vehicle Lights


Your vehicle's exterior lights with clear lenses are vented to the atmosphere to release pressure as the air inside heats and cools. When humid/moist air enters the headlight/tail light, the moisture may condense on the lens surface and appear as fogging or water droplets. This is a normal condition and the moisture will evaporate when the lights are turned ON or when the temperature increases.

USB Ports and Use of Cables



If you encounter difficulty plugging in a compatible USB device, change the orientation of the device (may be upside down). Always use the USB charging cable that has been certified by the device manufacturer. Use of aftermarket cables is **NOT** recommended as they may impact functionality.

Power Outlet*



(Located at rear of Center Console

The power outlet is designed to provide power for mobile telephones or other devices designed to operate with vehicle electrical systems. The devices should draw less than 12V, 15A with the engine running.

Use a power outlet only when the engine is running and remove the accessory plug after use. Using the accessory plug for prolonged periods of time with the engine off could cause the battery to discharge.

Only use devices designed to operate on a 12V (180W max) power outlet.





2018 Kia **Soul** has been awarded an overall 5-Star crash safety rating (the highest possible) by the National Highway Traffic Safety Administration (NHTSA). www.NHTSA.gov¹



2018 Kia **Forte** has been awarded an overall 5-Star crash safety rating (the highest possible) by the National Highway Traffic Safety Administration (NHTSA). www.NHTSA.gov¹



2018 Kia **Sorento** has been awarded a 5-Star overall safety rating (the highest possible) by the National Highway Traffic Safety Administration (NHTSA). www.NHTSA.gov¹



2018 Kia **Sedona** has been awarded a 5-Star overall safety rating (the highest possible) by the National Highway Traffic Safety Administration (NHTSA). www.NHTSA.gov¹



2018 Kia **Optima** has been awarded a 5-Star overall safety rating (the highest possible) by the National Highway Traffic Safety Administration (NHTSA). www.NHTSA.gov¹



2018 Kia **Sportage** AWD has been awarded an overall 5–Star crash safety rating (the highest possible) by the National Highway Traffic Safety Administration (NHTSA). www.NHTSA.gov¹



2017 Kia **Niro** named a 10 Best Hybrid Car Under \$40,000 by Kelley Blue Book's KBB.com.²



2018 Kia **Sedona** named a 2017 IIHS **"Top Safety Pick"** when equipped with optional Front Crash Prevention. - www.iihs.org